



Controlled Number: LF-FM-JSGC-18

Lang Feng Metallic Materials Co., Ltd. Changsha branch file powder

Dry mill vibration safety technology

- 1、 Before the operation to put on work clothes, work shoes, wear gloves and a dust mask.
- 2、 Should be carefully checked before starting the equipment properly, the screws are loose.
- 3、 Began to send cooling water, cooling water may not start if there is no equipment.
- 4、 First test run after the boot, before being confirmed no abnormalities after loading.
- 5、 Start the motor should be gradually transferred to the high speed at low speed.
- 6、 During the operation should concentrate, always check equipment operation, abnormal timely manner.
- 7、 The device is not parked on the device platform is prohibited.
- 8、 Do not use without protective cover or shield unstable dry mill.
- 9、 Cut off the power supply should be shut down after use.
- 10、 To clean the device class and field sanitation, should be required to maintain a clean, industrial equipment, materials and other display.

Langfeng Metallic professional manufacturer of the cermet rods, ZrC powder, NbC powder, Cr₃C₂ powder, VC powder, TaC powder, TiC powder, HfC powder, ...), compound carbide powder and cutter wheels.